

WIDWAY WFG. CO.-

PHONE: AREA CODE 312 451-1360

CHICAGO PHONE: 992-2250

10750 W. GRAND AVENUE . FRANKLIN PARK, ILL. 60131

$\underline{S} \ \underline{E} \ \underline{R} \ \underline{V} \ \underline{I} \ \underline{C} \ \underline{E} \qquad \underline{B} \ \underline{U} \ \underline{L} \ \underline{E} \ \underline{T} \ \underline{I} \ \underline{N}$

GAME: Gun Fight Cocktail Table

SUBJECT: Possible glass top breaking when using wrong length

mounting bolts to secure top assembly.

The front top assembly mounting bolt should be 3 inches REMEDY:

in length.

The two rear mounting bolts are 3½ inches in length and should not be used in front.

